SKIN+ACT




Facial Brush Skin Care Unit


SKU25364

PACKAGE CONTENTS

- These components are subject to change without prior notice.
- Appearance of product may differ from the image.



FRONT PANEL



INSTRUCTIONS OF USE

BEFORE TREATMENT:

- Scrub the skin surface with a wet pad.
- Using a steamer (or hot cloth) soften the skin surface to be treated.
- After skin-cleansing maintenance, it is advisable to daub some nutritional oil on the target skin surface.

STARTING TREATMENT

- Connect the power supply via the rear panel.
- Connect the accessories properly in the lateral panel.
- Choose the appropriate brush head according to the customer's skin type. In general, delicate or dry skin needs a soft brush head, while harder brushes can be used for rough or greasy skin.
- Turn on the "POWER" button.
- Adjust the desired "ROTATION", "ENERGY" and "TIMER".
- Press the "START/PAUSE" button to start the treatment.
- While holding the brush handgrip, adjust "ENERGY". The speed of rotation will increase as the adjusting angle is increased.

CAUTIONS

- Do not press the brush head excessively while it is running.
- Do not operate this instrument with any evident acid or alkaline substance.
- After the operation, turn the instrument off and disconnect the power cord.
- This function should not be used on customers who suffer from hypersensitive skin or dermatitis.
- If the capillary vessels in the skin are injured, do not cleanse the skin with this function.

MAINTENANCE

- After the operation, submerge the brush head in clear water with a little cleanser for 5 minutes. Then, after rinsing it, submerge it in alcohol for half an hour.
- The brush head must be disinfected using ultraviolet radiation and then kept in its original packaging.

TECHNICAL SHEET

Weights and sizes	Product size (cm)	20.7×22×7
	Gross weight (kg)	3.5
Electrical characteristics	Rated voltage	AC 100-240V
	Frecuency	50/60Hz
	Rated power	25 W

1-800-418-0830 TOLL FREE

1-818-834-6640 INTERNATIONAL

Address: 9667 Canoga Ave, Chatsworth, CA 91311

SKIN+ACT